

European Office

Taylor House • 34 Sherwood Road • Bromsgrove Worcestershire • B60 3DR • England


Tel: 44 (0) 1527 520 999 Fax: 44 (0) 1527 501 999 E-mail: info@sti-emea.com • Web: www.sti-emea.com

USA - Headquarters

2306 Airport Road • Waterford, Michigan 48327-1209 Phone: 248-673-9898 • Fax: 248-673-1246

Toll Free: 800-888-4784 • E-mail: info@sti-usa.com

Web: www.sti-usa.com



IMPORTANT


Do not attempt to install reflective beam guard until both the transmitter and reflective mirror have been perfectly aligned and tested according to the System Sensor installation directions furnished with detector unit.

INSTALLATION INSTRUCTIONS

- Center the wire guard over existing reflective beam housing making sure center cutout in wire guard is positioned over beam lens window.
- 2. Mark and drill (4) holes as shown in pictorial. The Beam Smoke Guard may be spray painted once prior to installation.

SERVICE

- 1. Periodic cleaning of Beam Smoke Guard is required to prevent buildup of dust and other matter.
- 2. To service the System Sensor unit, back off the (4) screws, rotate clamps and carefully remove wire guard. When reinstalling wire guard, care must be taken not to hit or bump the reflective beam housing or misalignment may occur.



Three year warranty or a one year limited warranty (from date of purchase) on most products. See website for details. Electronic warranty form at www.sti-usa.com/wc14.

INSTALLATION OF STI-9706/STI-9707 BEAM SMOKE GUARD

All specifications and information shown were current as of publication and are subject to change without notice.

